ANNUAL RISK AND CONDITION ASSESSMENT OF ASSETS AND AMENITIES

Schedule

1. FLOOD RELIEF DYKE

- Maintain an up to date diagram of the village drainage system
- Check visually, twice a year (April and November) the following items:
 - walk the whole dyke and check for collapse, silting, debris causing obstruction and excessive vegetation. Clear as required.
 - all land drains, run offs and gulleys including:
 - land drain from "Roy's" pond (crosses School Lane to the dyke) to ensure it runs freely into the dyke
 - run offs at bottom of Brattleby Hill (to be concreted by Highways).
 - road gulley outside School House
 - manhole at corner of School House and dyke
 - new head walls for erosion i.e. both sides of road
 - land drain running out of left hand field by headwall
 - stream under the road (B1398) and down fish pond belt
 - road gulleys on B1398 including outflow into Snowdrop wood.

2. VILLAGE SIGN

- Check general condition of post and sign
- Check top fixing of sign to post

3. STONE WALL ADJACENT TO SUB-STATION

Examine bowing wall for deterioration

4. ELECTRICITY SUB STATION (B1398)

Check for overgrown vegetation and contact National Grid if necessary

5. BUS SHELTER

- Check general condition
- Check defibrillator

6. TELEPHONE BOX

Check general condition

7. LAMP POSTS

Check general condition

8. PADDOCK

• Check condition of trees, hedges, gate, bench etc.

9. CHURCH GATE AND WAR MEMORIAL - B1398

- Paint gate as required
- Weed kill around gate/cut back hedge to path to church as required
- · Check condition of signboard
- Check/clean names on memorial

10. CHURCH GATE (THORPE LANE)

- Check condition
- Check tree branches around street lamp

11. CHURCH YARD

- Check gutters, downpipes and drainage from spire/parapet
- Weed kill path
- Check paths for condition
- Produce annual grass cutting rota

12. TREES ON MILLENIUM AVENUE AND MIDDLE STREET

- Inspect condition of trees
- Remove lower branches, tubes, supports as required

13. SPEED LIMIT/ VILLAGE SIGNS AND ROAD MARKINGS

Check condition of signs and markings

SPEED INDICATOR DEVICES (SID)

Check condition and function

14. NORTH LAY-BY

· Check condition of area

15. VILLAGE ROADS AND FOOTPATHS

 Check roads, paths and verges for deterioration, pot holes, overgrowth etc

16. SOUTH END

- Inspect Thorpe Lane flooding/gulleys
- Check condition of trees on Thorpe Lane
- Check dyke/run-off opposite Mr. Blackbourn's house
- Check condition of trees around Mr. Blackbourn's house

17. TREES AND HEDGES GENERALLY

- Observe condition of trees and hedges
- 18. EAST END OF PARISH (Brattleby Hill to Vulcan Lodge area)
 - Check generally
- 19. WEST END OF PARISH (Thorpe Lane to Cricket Till)
 - Check generally

ACTION LIST FROM INSPECTION ON 22 May 2018

Flood relief dyke, road gulleys etc.	<u>Action</u>
 MS to ask F Wilson to dredge dyke check old land drains feeding pond clear run off (Brattleby Hill) of silt clear blockage to fish pond belt in winter 	MS MS/RD Done MS
Brattleby Hill	
- watch Ash trees for die back	ongoing
Stone wall adjacent to Sub-Station	
Wall leaning along footpath. Write to advise the Wrights again	MS
Telephone Box	
- repaint in 2019	R Doyle
<u>Paddock</u>	
- cut hedge later in year	MS/AB
School Lane and Back Lane	
- provide replica water pump	MS
Church Gate and War Memorial	
notice board post needs replacingpaint gate and bottom of lamp postweed kill around gate	MS/JS ? AB
Trees on Millennium Avenue and Middle Street	
- Remove tubes, supports and lower branches	Ongoing
B1398	
- Replace missing speed repeater	Highways
South End	
cut back shrub growth to show grassed arearelocate speed indicator	AB MS

Hedges/Invasive Weeds

- cut back hedges along footpath opposite Stonewell House	Wrights
- cut back hedges either side of church gate	Wrights
- watch for re-growth of Japanese Knotweed	All
- form working parties to clear Himalayan Balsam	AB/MS

Thorpe Lane to Cricket Till

- repair pot holes and surface break up MS

Updated 24 May 2018

LIST OF WORKS TO BE REFERRED TO HIGHWAYS DEPARTMENT

- Check/clear all road gulleys throughout village
 Replace missing speed repeaters in village

May 2018